

Leading Beverage Producer



Problem

A leading North American beverage producer had a recurring buildup of microbial film on its bottling and canning lines in several plants, which led to frequent line stoppages and the need for intense manual cleaning.

Pyure Solution

After a site assessment, Pyure Dynamic Protection® was designed and installed at industrial scale to provide sanitization of the bottling and canning lines for one location.

Outcome

- *Line stoppages were reduced from every two days to every four days*
- *Time needed for manual cleaning were reduced from 12 to 4 man-hours*
- *Significantly more revenue and less operating cost*
- *The company also saw a reduction in odors within the plant*

Pyure installed solutions were subsequently deployed in five additional plants due to the dramatic improvements to the operation.

